











Assembly Instructions


22110-1







60 min








		22110-1
1	1	400*400*18MM
2	1	348*396*18MM
3A	1	398*477*18MM
3B	1	398*477*18MM
4	1	348*103*18MM
5	1	342*100*18MM
6A	1	332*80*18MM
6B	1	332*80*18MM
7	1	327*80*18MM
8	1	301*342*5MM






 ϕ 15x12 Ax12	 M6x35 Bx12	 ϕ 8x40 Cx10	 M3. 5x15 Dx12
 Ex2	 Fx8	 Gx8	




1



$$E=E1+E2$$



2



3





AX4



BX8




CX4





4




DX6





E2X2




5



AX8




6



7




Fx8




8




Gx4



9



10




11



DX6



E1X2



12

